

# Inspection Photos

API: 017-06303

Operator: CITATION OIL & GAS CORP

Inspection Date: 7/13/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06303 | Date: 7/13/2020

## Inspection Photos



**Photo 1.** Facing southeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06303 | Date: 7/13/2020

## Inspection Photos



**Photo 2.** Facing south at the location. The location is bare of vegetation and has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06303 | Date: 7/13/2020

## Inspection Photos



**Photo 3.** Facing east at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06303 | Date: 7/13/2020

## Inspection Photos



**Photo 4.** Facing west at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06303 | Date: 7/13/2020

## Inspection Photos



**Photo 4.** Facing east toward the surrounding undisturbed rangeland.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06303 | Date: 7/13/2020