

Inspection Photos

API: 017-06697

Operator: CITATION OIL & GAS CORP

Inspection Date: 7/13/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06697 | Date: 7/13/2020

Inspection Photos



Photo 1. Facing east along the former acces road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06697 | Date: 7/13/2020

Inspection Photos



Photo 2. Facing east toward the location. This area is bare of vegetation which is approximately 50'x30'.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06697 | Date: 7/13/2020

Inspection Photos



Photo 3. Facing northwest toward the location. There are areas bare and sparse of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06697 | Date: 7/13/2020

Inspection Photos



Photo 4. Facing east toward the surrounding undisturbed rangeland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06697 | Date: 7/13/2020