

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/20/2020

Submitted Date:

07/20/2020

Document Number:

693503184

### FIELD INSPECTION FORM

Loc ID 323151 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                                | Comment         |
|--------------|-------|--------------------------------------|-----------------|
|              |       | Cogcc.inspections@crestone<br>pr.com | ALL INSPECTIONS |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 244835      | WELL | PA     | 03/21/2019  | GW         | 123-12630 | COSSLETT B UNIT 1X | PA          |
| 420750      | WELL | SI     | 12/01/2018  | GW         | 123-32702 | COSSLETT 8-2-22    | SI          |
| 420754      | WELL | SI     | 12/01/2018  | OW         | 123-32703 | COSSLETT 42-22     | SI          |
| 420757      | WELL | PA     | 12/06/2018  | GW         | 123-32704 | COSSLETT 6-0-22    | PA          |
| 420759      | WELL | SI     | 12/01/2018  | GW         | 123-32705 | COSSLETT 41-22     | SI          |
| 420763      | WELL | SI     | 12/01/2018  | OW         | 123-32706 | COSSLETT 4-0-22    | SI          |
| 420875      | WELL | SI     | 12/01/2018  | GW         | 123-32731 | COSSLETT 32-22     | SI          |
| 420884      | WELL | SI     | 12/01/2018  | GW         | 123-32736 | COSSLETT 6-4-22    | SI          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                   |       |  |
|--------------------|-------------------|-------|--|
| Type               | WELLHEAD          |       |  |
| Comment:           | Chain link        |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | IGNITOR/COMBUSTOR |       |  |
| Comment:           | Chain link        |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | TANK BATTERY      |       |  |
| Comment:           | Chain link        |       |  |
| Corrective Action: |                   | Date: |  |

**Equipment:**

|                     |     |       |                 |
|---------------------|-----|-------|-----------------|
| Type: Gas Meter Run | # 1 |       | corrective date |
| Comment:            |     |       |                 |
| Corrective Action:  |     | Date: |                 |
| Type: Bradenhead    | # 6 |       |                 |
| Comment:            |     |       |                 |
| Corrective Action:  |     | Date: |                 |
| Type: Plunger Lift  | # 6 |       |                 |

|                                   |     |       |  |
|-----------------------------------|-----|-------|--|
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Horizontal Heated Separator | # 4 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Bird Protectors             | # 7 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | PBV FIBERGLASS |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 235bbl   |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity                                 | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|-------------|
|                    |  |                     |                     |             |
| Comment:           | Shares containment with crude oil tanks. |                     |                     |             |
| Corrective Action: |  |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 4 | OTHER    | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 330bbl   |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|        |    |  |  |
|--------|----|--|--|
| Yes/No | NO |  |  |
|--------|----|--|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |   |   |           |             |           |         |    |               |       |  |
|----------------------|---|---|-----------|-------------|-----------|---------|----|---------------|-------|--|
| Facility ID:         | 244835                                      | Type:   | WELL      | API Number: | 123-12630 | Status: | PA | Insp. Status: | PA    |  |
| <b>Idle Well</b>     |   |   |           |             |           |         |    |               |       |  |
| Purpose:             | <input type="checkbox"/> Shut In            | <input checked="" type="checkbox"/> Temporarily Abandoned | Reminder: |             |           |         |    |               |       |  |
| Comment:             | P&A   |   |           |             |           |         |    |               |       |  |
| Corrective Action:   |   |   |           |             |           |         |    |               | Date: |  |
| Facility ID:         | 420750                                      | Type:   | WELL      | API Number: | 123-32702 | Status: | SI | Insp. Status: | SI    |  |
| <b>Idle Well</b>     |   |   |           |             |           |         |    |               |       |  |
| Purpose:             | <input type="checkbox"/> Shut In            | <input checked="" type="checkbox"/> Temporarily Abandoned | Reminder: |             |           |         |    |               |       |  |
| Comment:             | SI Tubing flow lines have been removed      |   |           |             |           |         |    |               |       |  |
| Corrective Action:   |   |   |           |             |           |         |    |               | Date: |  |
| Facility ID:         | 420754                                      | Type:   | WELL      | API Number: | 123-32703 | Status: | SI | Insp. Status: | SI    |  |
| <b>Idle Well</b>     |   |   |           |             |           |         |    |               |       |  |
| Purpose:             | <input checked="" type="checkbox"/> Shut In | <input type="checkbox"/> Temporarily Abandoned            | Reminder: |             |           |         |    |               |       |  |
| Comment:             | SI Tubing flow lines have been removed      |   |           |             |           |         |    |               |       |  |
| Corrective Action:   |   |   |           |             |           |         |    |               | Date: |  |
| Facility ID:         | 420757                                      | Type:   | WELL      | API Number: | 123-32704 | Status: | PA | Insp. Status: | PA    |  |
| <b>Idle Well</b>     |   |   |           |             |           |         |    |               |       |  |
| Purpose:             | <input type="checkbox"/> Shut In            | <input checked="" type="checkbox"/> Temporarily Abandoned | Reminder: |             |           |         |    |               |       |  |
| Comment:             | P&A   |   |           |             |           |         |    |               |       |  |
| Corrective Action:   |   |   |           |             |           |         |    |               | Date: |  |
| Facility ID:         | 420759                                      | Type:   | WELL      | API Number: | 123-32705 | Status: | SI | Insp. Status: | SI    |  |
| <b>Idle Well</b>     |   |   |           |             |           |         |    |               |       |  |
| Purpose:             | <input checked="" type="checkbox"/> Shut In | <input type="checkbox"/> Temporarily Abandoned            | Reminder: |             |           |         |    |               |       |  |
| Comment:             | SI Tubing flow lines have been removed      |   |           |             |           |         |    |               |       |  |
| Corrective Action:   |   |   |           |             |           |         |    |               | Date: |  |
| Facility ID:         | 420763                                      | Type:   | WELL      | API Number: | 123-32706 | Status: | SI | Insp. Status: | SI    |  |
| <b>Idle Well</b>     |   |   |           |             |           |         |    |               |       |  |
| Purpose:             | <input checked="" type="checkbox"/> Shut In | <input type="checkbox"/> Temporarily Abandoned            | Reminder: |             |           |         |    |               |       |  |
| Comment:             | SI Tubing flow lines have been removed      |   |           |             |           |         |    |               |       |  |
| Corrective Action:   |   |   |           |             |           |         |    |               | Date: |  |
| Facility ID:         | 420875                                      | Type:   | WELL      | API Number: | 123-32731 | Status: | SI | Insp. Status: | SI    |  |

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment:

Corrective Action:       Date: \_\_\_\_\_

Facility ID: 420884    Type: WELL    API Number: 123-32736    Status: SI    Insp. Status: SI

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment:

Corrective Action:       Date: \_\_\_\_\_

**COGCC Comments**

| Comment  | User    | Date       |
|--|---------|------------|
| Routine inspection. At time of inspection crew was blowing down wells to prep for P&A and TA ing of wells. Spoke with operator and proper forms are being submitted to preform work. | silverr | 07/20/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 693503185    | loc pic     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5199438">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5199438</a> |