

# Inspection Photos

7/17/2020

Operator: BERRY PETROLEUM COMPANY LLC  
- 10091

Location ID: 335964

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335964



**Photo 1:** Photo shows the 2 active wells on the Location.



## Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335964



**Photo 2:** Photo taken from the south end of the Pad, facing west. Photos 2-4 provide an overview of the Location from west, north to east.

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335964



**Photo 3:** See comments under photo 2.

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335964



**Photo 4:** See comments under photo 2.

## Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335964



**Photo 5:** Photo taken from the southern interim areas, facing west. Photo shows desirable vegetative establishment appears to be progressing towards COGCC 1000 series requirements.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335964



**Photo 6:** Photo taken from the northern interim areas, facing east. Photo shows desirable vegetative establishment DOES NOT appear to be progressing towards COGCC 1000 series requirements; Additional revegetation activities will likely be needed for areas to meet reclamation standards.



## Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335964



**Photo 7:** Photo taken from the northern interim areas. Photo shows Bull thistle (*Cirsium vulgare*) is establishing in the northern interim areas. This is a Colorado State listed noxious weed; Management required.



## Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335964



**Photo 8:** Photo taken from the northern interim areas, facing north. Photo shows Bull thistle (*Cirsium vulgare*) is establishing in the northern interim areas. This is a Colorado State listed noxious weed; Management required.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources