

Inspection Photos

7/17/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335999

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335999



Photo 1: Photo taken from the east end of the Location, facing southwest. Photos 1-3 provide an overview of the Location and interim areas from south, west to north.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335999



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335999



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335999



Photo 4: Photo shows active wells on the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335999



Photo 5: Photo taken from the northwest corner of the pad, facing north. Photo shows portable pumping unit; Small leak observed from a valve on the pump resulting in produced fluids discharging on to the pad surface.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335999



Photo 6: Photo of valve on the portable pump resulting in produced fluid discharge.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335999



Photo 7: Photo of portable pump and the leaked produced fluids. Photo also shows liner placed under the equipment. BMP insufficient to contain spill .



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335999



Photo 8: Continued from photo 7. Photo shows liner placed under the equipment is insufficient to contain spilled fluids and prevent discharge onto pad surface



Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 335999



Photo 9: Photo taken west end of the tank battery. Photo shows pipe connecting battery to the pump.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335999



Photo 10: Photo taken west end of the tank battery. Photo shows pipe connecting battery to the pump.

