

Inspection Photos

7/17/2020

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324382

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 324382




Photo 1: 2005 Google earth aerial imagery. Photo shows location pre oil and gas disturbance.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 324382



Photo 2: 2011 Google earth aerial imagery. Photo shows location post oil and gas disturbance.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324382



Photo 3: Photo taken from the central area of the Location, facing northeast. Photo shows soil stockpile on Location. Location requires contouring and soils replaced and reclaimed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324382



Photo 4: Photo taken from the north end of the Location, facing west. Photo shows soil stockpile remaining on Location. Photo also shows large areas of the Location that remains predominantly bare and exposed soils.

