

Inspection Photos
Location Name: Badding Tank Battery
Location ID: 421518



Photo 1 TB/signs

Photo 2 TB

Inspection Photos
Location Name: Badding Tank Battery
Location ID: 421518



Photo 3 LACT

Photo 4 ECD horizontal Heated Separators

Inspection Photos
Location Name: Badding Tank Battery
Location ID: 421518



Inspection Photos
Location Name: Badding Tank Battery
Location ID: 421518



Colorado Oil & Gas Conservation Commission
 16500 Casler Ave, Fort Lupton, CO 80621, USA
 40.10851, -104.7429, 5024.8ft, 358°
 07/20/2020 13:49:09



Colorado Oil & Gas Conservation Commission
 16500 Casler Ave, Fort Lupton, CO 80621, USA
 40.10851, -104.7429, 5013.4ft, 340°
 07/20/2020 13:49:31

Photo 7 Gas Meter Run

Photo 8 Card inside meter house indicates current calibration

Inspection Photos
Location Name: Badding Tank Battery
Location ID: 421518



Photo 9 Gas Meter Run

Photo 10 Card inside meter house indicates current calibration

Inspection Photos
Location Name: Badding Tank Battery
Location ID: 421518



Photo 11 Horizontal Heated Separators

Photo 12 VRU

Inspection Photos
Location Name: Badding Tank Battery
Location ID: 421518



Photo 13 Horizontal Heated Separators

Photo 14 VRU

Inspection Photos
Location Name: Badding Tank Battery
Location ID: 421518



Photo 15 ECDs