

Inspection Photos  
Location Name: Marcus State W36-06JFI  
Location ID: 332434



Photo 1 WH sign



Photo 2 WH

**Inspection Photos**  
**Location Name: Marcus State W36-06JFI**  
**Location ID: 332434**



**Photo 3 TB sign**



**Photo 4 TB**

Inspection Photos  
Location Name: Marcus State W36-06JFI  
Location ID: 332434



Photo 5 Gas Meter Run




Photo 6 Card inside meter house indicates that calibration is not current



**Inspection Photos**  
**Location Name: Marcus State W36-06JFI**  
**Location ID: 332434**



**Photo 7 Horizontal Heated Separator**