

Inspection Photos
Location Name: CORNISH-66N63W /3NWNW
Location #: 332492



Photo #1
Cornish 11-3 (05-123-22375) Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | Final Plugging



Photo #2
Cornish 11-3 Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | Final Plugging
Cement to surface
NOT Cut & Capped

Inspection Photos
 Location Name: CORNISH-66N63W /3NWNW
 Location #: 332492



Photo #3
 Cornish 11-3 Wellsite
 Plugged & Abandoned | PA
 Rig safety sign



Photo #4
 Cornish 11-3 Wellsite
 Plugged & Abandoned | PA
 Jobsite Manifest