

Inspection Photos

Location Name: LARAMIE ENERGY LLC Piceance /29-07

Location ID: 334436



Photo #1560 from entrance to location



Photo #1561 from entrance to location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Piceance /29-07

Location ID: 334436



Photo #1562 Multiple places with stained soils at wellheads.



Photo #1563 Multiple places with stained soils at wellheads.