

Inspection Photos

API: 073-06743

Operator: K3 OIL & GAS OPERATING COMPANY

Inspection Date: 7/14/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06743 | Date: 7/14/2020

Inspection Photos



Photo 1. Facing east along the reclaimed access road. Vegetation appears to be germinating and establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 7/14/2020

Inspection Photos



Photo 2. Facing east at the location. The location has been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 7/14/2020

Inspection Photos



Photo 3. View of groundcover at the location shows soils were straw mulched for temporary stabilization. There is desirable grasses beginning to grow and also some undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 7/14/2020

Inspection Photos



Photo 4. Facing north at center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 7/14/2020

Inspection Photos



Photo 5. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 7/14/2020