

# Inspection Photos

API: 073-06615

Operator: PIONEER NATURAL RESOURCES USA INC

Inspection Date: 7/14/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 1.** Facing northeast at the beginning of the access road. The access road is bare of vegetation along the majority of the road to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 2.** Facing northeast along the access road. The access road is bare of vegetation along the majority of the road to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 3.** Facing east along the access road. The access road is bare of vegetation along the majority of the road to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 4.** Facing east along the former road near the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 5.** Facing east at the location. Most of the location is bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 6.** Facing northeast at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 7.** Southeast corner facing northwest. Most of the location is bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 8.** This photo shows a comparison of the undisturbed reference area on the right side of photo and the disturbed location on the left side.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 9.** Facing south at center of the location. There are some areas of rill erosion that had occurred.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 10.** North side of the location facing south.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 11.** Northwest side of the location facing south.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020

## Inspection Photos



**Photo 12.** Facing southeast toward the surrounding rangeland.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06615 | Date: 7/14/2020