

Inspection Photos

Operator: Paradox Upstream
API: 113-06126
Date: 7/14/2020



Photo 1. View of the project area from the southeaster corner facing center.



Photo 2. View of the southern interim reclamation area, facing westward, comprised of western wheatgrass, rubber rabbitbrush, sand dropseed, and James galleta.



Photo 4. View of erosional channels flowing off of the southern portion of the well pad. Channels are approximately 1-2 feet deep and 2-4 feet wide and need stabilization.



Photo 4. View of more erosional channels within the southern project area.



Photo 5. View of reference area comprised of black sage shrubland with needle and thread grass, blue grama, snakeweed, and sand heath.