

# Inspection Photos

Operator: Paradox Upstream  
API: 113-06108  
Date: 7/14/2020



Photo 1. View of the project area from the northern edge of the well pad, facing center.





Photo 2. View of the eastern reclamation area from the northeastern corner facing northward. Revegetation is progressing and is comprised of grasses and shrubs such as western wheatgrass, crested wheatgrass, and fourwing saltbush.





Photo 3. View of the northwestern project area facing southward.



Photo 4. View of reference area comprised of black sage shrubland with needle and thread grass, blue grama, snakeweed, and sand heath.