

**Inspection Photos**  
**Operator: Paradox Upstream**  
**API: 113-06003**  
**Date: 7/14/2020**



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the western reclamation area from the southwestern corner facing northward. Revegetation is progressing and is comprised of grasses and shrubs such as western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of the eastern project area facing southward.



Photo 4. View of reference area comprised of black sage shrubland with needle and thread grass, blue grama, snakeweed, and sand heath.