

Inspection Photos

Operator: Paradox Upstream
API: 113-06115
Date: 7/14/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing westward. Revegetation is progressing and is comprised of grasses and shrubs such as western wheatgrass, crested wheatgrass, blue grama, fourwing saltbush, and winterfat.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of reference area comprised of black sage shrubland with needle and thread grass, blue grama, snakeweed, and sand heath.