

# Inspection Photos

Operator: Paradox Upstream  
API: 113-06252  
Date: 7/14/2020



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing and is comprised of grasses and shrubs such as western wheatgrass, crested wheatgrass, fourwing saltbush, and rubber rabbitbrush.





Photo 3. View of erosional channel forming at the well pad entrance. Channel is approximately 2 feet wide and 1 foot deep and needs stabilization.



Photo 4. View of reference area comprised of black sage shrubland with needle and thread grass, blue grama, snakeweed, and sand heath.