

Inspection Photos

API#045-11304

Operator: Terra

Inspection Number: 692402184

Inspection Date: 5/12/20





Photo#1:
Overview of Location to East.

May 12, 2020



Photo#2:
Woven wire bits of fencing within Location barb wire exclusion fencing.

May 12, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#3:
Woven wire bits of fencing within Location barb wire exclusion fencing.

Inspection Photos: Terra PA Potter HM API#045-11304



Photo#4:
View North over Location center.

Photo#5:
View South over Location center.

May 12, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PA Potter HM API#045-11304



Photo#6:
View East over Location center.



Photo#7:
View West over Location center.

May 12, 2020