

Inspection Photos
Location Name: Denali 15-12
Location ID: 313099

Click Here to Request the Form
 State of Colorado
 Oil and Gas Conservation Commission

MECHANICAL INTEGRITY TEST

Well Name: 5918-5904 Well ID: 5918-5904 Well Type: Oil

Operator: WELLS SERVICE COMPANY Well Status: Producing

Test Date: 7/21/20 Test Time: 14:00 Test Duration: 10 min

Test Type: ☒ **SUIT IN PRODUCTION WELL** ☐ **INJECTION WELL**

Test Location: Wellhead Test Depth: 140 ft Test Pressure: 1000 psi

Test Results: Pass Test Comments: Leak 5 psi during final 5 min. continued test for additional 5 min and pressure held.

Inspector: Don Belter Date: 7/21/20

Inspector Title: Field Inspector

Inspection doc # 689504451

Photo 1. Photo of Form 21 as filled out in the field.

