

Inspection Photos

6/23/2020

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335275

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335275



Photo 1: Photo taken from the west end of the Location, facing southwest. Photo shows areas of the stormwater diversion ditch where Halogeton was observed. Photo also shows sediment deposition within the ditch; Maintenance advised.



Photo 2: Continued from photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335275



Photo 3: Photo taken from the west end of the Location, facing west. Photo shows slopes where stormwater appears to be undercutting rocks on the slopes. COGCC strongly recommends that appropriate precautions are taken by the Operator due to potential rock fall from these areas not disturbed during construction.



Photo 4: Photo taken from the Location facing northeast. Photo shows slopes on the northeast end of the Location with insufficient or missing BMPs to stabilize and protect slopes/soils.