

Inspection Photos
Location Name: Conner 22-34
Location ID: 319538



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Conner 22-34
Location ID: 319538



Photo 3 TB signs

Photo 4 TB

Inspection Photos
Location Name: Conner 22-34
Location ID: 319538




Photo 5 ECD

Photo 6 Horizontal Heated Separator

Inspection Photos
Location Name: Conner 22-34
Location ID: 319538



Colorado Oil & Gas Conservation Commission
 3211 14 St, Fort Lupton, CO 80621, USA
 40.09608, -104.76545, 4980.3ft, 296°
 07/21/2020 13:29:18



Test Date	Cell Size	Notes	Sample Date	H2O	Sample Date	H2O	C ₂	Gravity
8/2/18	1.25		8/2/18	2.0				
11/2/18	1.25		11/2/18	2.0				
3/26/19	1.25		3/26/19	2.0				
5/26/19	1.25		5/26/19	2.0				
7/25/19	1.25		7/25/19	2.0				
9/25/19	1.25		9/25/19	2.0				
11/25/19	1.25		11/25/19	2.0				
3/26/20	1.25		3/26/20	2.0				

Colorado Oil & Gas Conservation Commission
 3211 14 St, Fort Lupton, CO 80621, USA
 40.09613, -104.76544, 4982.9ft, 326°
 07/21/2020 13:29:50

Photo 7 Gas Meter Run

Photo 8 Card in meter house indicates current calibration