

Inspection Photos
Location Name: Steve J Pad
Location ID: 333001



Photo 1: Tank Battery Sign



Photo 2: Erosion repaired

Inspection Photos
Location Name: Steve J Pad
Location ID: 333001



Colorado Oil and Gas Conservation Commission
40.3993, -104.82217, 1498.4m, 345°
Jul 23, 2020 15:00:26

Photo 3: Erosion repaired



Colorado Oil and Gas Conservation Commission
40.39935, -104.82254, 1500.7m, 276°
Jul 23, 2020 14:59:11

Photo 4: Hole in load out bucket

Inspection Photos
Location Name: Steve J Pad
Location ID: 333001



Photo 5: Unused/disconnected gas meters



Photo 6: Hole in berm wall