

Inspection Photos

API#077-08582

Operator: Caerus

Inspection #: 692402372

Inspection Date: 7/16/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest and entry

July 16, 2020



Photo#2:
Cattle leaving Location.

July 16, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Divide Creek API#077-08582



Photo#3:
Valve can remaining on site.

July 16, 2020



Photo#4:
Line inside valve can.



Photo#5:
Poly line on site.



Photo#6:
Poly line on site.

July 16, 2020