

# *Inspection Photos*

*Loc#418340*

*Operator: Grizzly*

*Inspection Number: 692402377*

*Inspection Date: 7/20/2020*





**Photo#1:**  
Overview of Location to South and upper tier housing equipment.

July 20, 2020



Photo#2:  
View along cut slope and Russian thistle establishment.

Photo#3:

July 20, 2020



Photo#4:

Site degradation, erosion and undermining of root systems is occurring.

Photo#5:

July 20, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Grizzly Kaufman Loc#418340