

# Inspection Photos

Operator: Paradox Upstream  
API: 113-06227  
Date: 7/15/2020



Photo 1. View of the project area from the southern edge facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing and is comprised of grasses and shrubs such as western wheatgrass, crested wheatgrass, rubber rabbitbrush.





Photo 3. View of the western project area from the southwestern corner facing northward.





Photo 4. View of musk thistles within the southeastern project area. Approximately 100 individuals observed.





Photo 5. View of salt cedar trees within the southeastern project area.





Photo 6. View of reference area comprised of pinyon and juniper woodland with understory of big sagebrush, blue grama, and sand heath.