

Inspection Photos
Operator: Paradox Upstream
API: 113-06133
Date: 7/15/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing and is comprised of grasses and shrubs such as western wheatgrass, blue grama, and fourwing saltbush, as well as weeds such as cheatgrass.



Photo 3. View of the southern project area from the southwestern corner facing eastward.




Photo 4. View of Russian knapweeds (~300) growing along the access road.



Photo 5. View of young salt cedar tree becoming established on the well pad.



Photo 6. View of reference area comprised of pinyon and juniper woodland with understory of big sagebrush, blue grama, and sand heath.