

Inspection Photos

Operator: Paradox Upstream
API: 113-06054
Date: 7/16/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the northern project area from the southwestern corner facing northeastward. Revegetation is progressing and is comprised of grasses and shrubs such as western wheatgrass, blue grama, and fourwing saltbush, as well as weeds such as cheatgrass. Location is infested with approximately 1000 diffuse knapweeds.



Photo 3. View of unused equipment and open pipe in the project area.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of big sagebrush, blue grama, and sand heath.