

Inspection Photos
Location Name: Razor 25M PAD
Location ID: 444387



Photo 1 – North Wellheads

Photo 2 – South Wellheads

Inspection Photos
Location Name: Razor 25M PAD
Location ID: 444387





Photo 3 – 25M-2403 missing Wellhead Sign

Photo 4 – 25M-2401 missing Wellhead Sign