

# Interim Reclamation Inspection

July 21, 2020

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 428225

Inspection Document #: 697501781

Weld County, CO

NWSW Section 5 T7N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location: Leggett #1-5H  
Location ID: 428225



**Photo 1.** Photo taken from the southern well pad, facing Northwest. Photo illustrates Operator has initiated interim reclamation activities but still has the majority of the work to perform.

Inspection Photos  
Location: Leggett #1-5H  
Location ID: 428225



**Photo 2.** Photo taken from the southern well pad, facing Northeast. See comments under Photo 1.