

Location ID: 454560



Photo #1 Location



Photo #2 Stained Soil around wells

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #3 Trash



Photo #4 Appears to be leaking hammer unions at hi/low valves on various separators.

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #5 Appears to be leaking hammer unions at hi/low valves on various separators.




Photo #6 Unused equipment

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #7 Unused Equipment



Photo #8 Trash

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #9 Trash




Photo #10 Trash

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560




Photo #11 Unreadable placard/ missing capacity label



Photo #12 Unreadable placard/ missing capacity label

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #13 Stained soil



Photo #14 Stained soil

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560




Photo #15 Stained soil



Photo #16 Stained soil



Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #17 Unused Equipment



Photo #18 Unused Equipment

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #19 Unused equipment



Photo #20 Unused equipment

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #21 Trash



Photo #22 Trash

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #23 Unused equipment



Photo #24 Trash, Barrel needs to be in secondary containment, Inadequate wildlife protections (netting) of secondary containments.

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #25 Inadequate wildlife protections (netting) of secondary containments.



Photo #26 Inadequate wildlife protections (netting) of secondary containments.

Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #27 Needs bird protector



Photo #28 Needs bird protector



Inspection Photos
Location Name: 70 Ranch 10 West
Location ID: 454560



Photo #29 Needs secondary containment/ Trash

