

Inspection Photos
Location Name: James S. Haley Trustee #3
Location ID: 318296



Photo 1 WH sign faded will need replaced in the near future

Photo 2 WH

Inspection Photos
Location Name: James S. Haley Trustee #3
Location ID: 318296



Photo 3 Weeds growing along access road

Photo 4 Pump Jack

Inspection Photos
Location Name: James S. Haley Trustee #3
Location ID: 318296



Photo 5 Weeds growing well site ROW