

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 312598



Photo #1569 from entrance to location



Photo #1570 Multiple places with weeds and debris on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 312598



Photo #1571 Multiple places with weeds and debris on location.