

## Inspection Photos

Location Name: GUNNISON ENERGY LLC SPAULDING PEAK 1294-612S94W /23NWSE

Location ID: 321999



Photo #1577 from entrance to location



Photo #1578 Multiple places with unused equipment.

## Inspection Photos

Location Name: GUNNISON ENERGY LLC SPAULDING PEAK 1294-612S94W /23NWSE

Location ID: 321999



**Photo #1579 Multiple places with unused equipment.**