

Inspection Photos

Location Name: LARAMIE ENERGY LLC Bruton /30-03 Pad

Location ID: 451421



Photo #1592 from entrance to location



Photo #1593 Multiple places with stained soils by wellheads.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Bruton /30-03 Pad

Location ID: 451421



Photo #1596 Multiple places with stained soils by wellheads.



Photo #1598 Multiple places with stained soils by wellheads.