

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2020

Submitted Date:

07/24/2020

Document Number:

679603108**FIELD INSPECTION FORM**Loc ID 332925 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274899	WELL	PA	06/10/2019	GW	123-25604	SAMUEL J 7-9	PA
274900	WELL	TA	06/01/2019	GW	123-25605	SAMUEL J 7-15	PA
274901	WELL	SI	05/01/2019	OW	123-25606	SAMUEL J 7-16	PA
274902	WELL	SI	01/01/2017	OW	123-25607	SAMUEL J 7-23	PA

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 274899 Type: WELL API Number: 123-25604 Status: PA Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: PA
Form 6(S) DOC#: 402110780 in well file.

Corrective Action: Date:

Facility ID: 274900 Type: WELL API Number: 123-25605 Status: TA Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: PA
Form 42 DOC#: 402080703 in well file. Awaitn Form 6(S) to be filed for completions of PA operations.

Corrective Action: Date:

Facility ID: 274901 Type: WELL API Number: 123-25606 Status: SI Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: PA
Form 6(S) DOC#: 402403183 (in process) in well file.

Corrective Action: Date:

Facility ID: 274902 Type: WELL API Number: 123-25607 Status: SI Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: PA
Form 6(S) DOC#: 402000571 (in process) in well file.

Corrective Action: Date:

COGCC Comments

Comment	User	Date
No evidence of oil and gas production at location. All productive equipment has been removed. **Weather Conditions: sunny, dry ground	santistb	07/24/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603108	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5203914
679603109	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5203907