

Inspection Photos
Location Name: UPRC 23-3E
Location ID: 329775




Wellhead and weeds on 7/10/2020



Wellhead and weeds on 7/22/2020

Inspection Photos
Location Name: UPRC 23-3E
Location ID: 329775



Variance tag and weeds on 7/10/2020



Variance tag and weeds on 7/22/2020