

**Inspection Photos**  
**Location Name: Badding Tank Battery 35N-2HZ**  
**Location ID: 319049**



**Photo 1 TB signs**

**Photo 2 TB**

## Inspection Photos

Location Name: Badding Tank Battery 35N-2HZ

Location ID: 319049



Photo 3 LACT house

Photo 4 Electric panels / VRU

**Inspection Photos**  
**Location Name: Badding Tank Battery 35N-2HZ**  
**Location ID: 319049**



**Photo 5 ECD**

**Photo 6 Horizontal Heated Separators**

**Inspection Photos**  
**Location Name: Badding Tank Battery 35N-2HZ**  
**Location ID: 319049**



Colorado Oil & Gas Conservation Commission  
 17000 9th St, Fort Lupton, CO 80621, USA  
 40.08973, -104.74709, 5038.8ft, 46°  
 07/22/2020 11:07:01



Colorado Oil & Gas Conservation Commission  
 17089 9th St, Fort Lupton, CO 80621, USA  
 40.08974, -104.74702, 5038.2ft, 347°  
 07/22/2020 11:07:22

**Photo 7 Gas Meter Run**

**Photo 8 card in meter house indicates current calibration**