

Inspection Photos

Operator: Paradox Upstream
API: 113-06047
Date: 7/15/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing and is comprised of grasses and shrubs such as western wheatgrass, crested wheatgrass, rubber rabbitbrush.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of big sagebrush, blue grama, and sand heath.