

# Final Reclamation Inspection

July 21, 2020

Operator: BISON OIL & GAS II LLC - #10661

Location ID: 468699

Inspection Document #: 697501775

Weld County, CO

NENW Section 21 T8N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Goldeneye /East Pad  
Location ID: 468699



**Photo 1.** Photo taken from the location, facing South. Photo illustrates location was not constructed at the proposed well location based off field observations.