

Final Reclamation and Stormwater Inspection

July 21, 2020

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 426701

Inspection Document #: 697501779

Weld County, CO

Lot 3 Section 1 T7N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 1. Photo taken from the entrance of location, facing South. Photo illustrates Operator has completed final reclamation activities with the evidence of germination.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 2. Photo taken from the entrance of location, facing South. Photo illustrates the access to the left of the red-dashed line and the reference area to the right of the red-dashed line.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 3. Photo taken from a portion of the access road, facing Southeast. See comments under Photo 1.