

Inspection Photos
Location Name: Wagner 2-1
Location ID: 323293



Tank battery



Wellhead

Inspection Photos
Location Name: Wagner 2-1
Location ID: 323293



Colorado Oil And Gas Conservation Commission
40.34705, -104.8625, 1468.0m
07/15/2020 9:16:14 AM

Debris



Colorado Oil And Gas Conservation Commission
40.3374, -104.86731
07/15/2020 9:16:36 AM

Debris

Inspection Photos
Location Name: Wagner 2-1
Location ID: 323293



Master valve leak and stained soil