

Final Reclamation Inspection

July 13, 2020

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 446029

Inspection Document #: 697501758

Weld County, CO

NENE Section 25 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Walton 8,17-25 Tank Battery

Location ID: 446029



Photo 1. Photo taken from the eastern tank battery, facing West. Photo illustrates the tank battery is bare soil with no establishment of desirable vegetation, only some weed establishment.

Inspection Photos
Location Name: Walton 8,17-25 Tank Battery
Location ID: 446029



Photo 2. Photo taken from the central tank battery, facing Northwest.
See comments under Photo 1.

Inspection Photos
Location Name: Walton 8,17-25 Tank Battery
Location ID: 446029



Photo 3. Photo taken from the southern tank battery, facing West. Photo illustrates the establishment of field bindweed, a List C Colorado noxious weed.