

Inspection Photos

7/14/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335622

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335622



Photo 1: Photo taken from the east end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335622



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335622



Photo 5: Photo taken from the Location. Photo shows example of noxious weeds (Halogeton) observed throughout the production areas. This is a Colorado State listed noxious weed and requires management.



Photo 6: Photo taken from the south of the wells, facing north. Photo shows unmarked anchor.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335622



Photo 7: Photo taken from the west of the wells, facing east. Photo shows unmarked anchor.



Photo 8: Photo taken from the west end of the Location facing west. Photo shows interim areas.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335622



Photo 9: Photo of sediment trap on the south end of the Location.



Photo 10: Continued from photo 9. Photo shows inlet at the trap.