

BP L48 San Juan



V2 Compliance Follow Up Form

18149211457

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200722-18149211457

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Jul 22, 2020 11:20:32 AM MDT

557 Airpark Dr, Durango, CO 81303, USA

Jul 22, 2020 11:23:33 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jul 21, 2020

Well Name

CONRAD GAS UNIT B 1

API Number

50670713800

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Seeding

Photo of first corrective action completed



Completed work description Corrective
Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

seeding and blanket on slope

Photo of third corrective action completed



Completed work description of corrective action 3

seeding and blanket on slope

Photo of fourth corrective action completed



Completed work description	seed
Completed work description of corrective action 4	seeded and blanketed slopes
Completed work description	seeded and blanketed slopes

Summary of all work completed

seeded and blanketed slopes with 100%
biodegradable blanket