

BP L48 San Juan



V2 Compliance Follow Up Form

18149190961

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200722-18149190961

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Jul 22, 2020 8:42:52 AM MDT

Unnamed Road, Ignacio, CO 81137, USA

Jul 22, 2020 8:39:18 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Jul 17, 2020
Well Name	TUBBS GAS UNIT 32-6-9 B 2
API Number	50670895500
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Clean up Operator Debris Clean Up Contaminated Soils Spot seeding Removed sediment from BMP's
Photo of first corrective action completed	



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



**Completed work description of corrective
action 2**

Built diversion ditch

Photo of third corrective action completed



**Completed work description of corrective
action 3**

Installed rock run down

Photo of fourth corrective action completed



Completed work description

Cleaned up stains

Completed work description of corrective action 4

Marked anchors

Additional photos



Additional photos



Additional photos

**Summary of all work completed**

Compliance, cleaned up stains , installed rock run down , cleaned up trash installed diversion ditch spot seeded and marked anchors.