

BP L48 San Juan



V2 Compliance Follow Up Form

18149189200

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200722-18149189200

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Jul 22, 2020 8:10:32 AM MDT

2287 Co Rd 330, Ignacio, CO 81137, USA

Jul 22, 2020 8:08:10 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Jul 20, 2020
Well Name	BROWN GAS UNIT 32-6-03 2
API Number	50670877900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Other Install Rock Run Down Clean Up Land Owner Debris Clean Up Contaminated Soils Spot seeding

Photo of first corrective action completed



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Spot seeded

Photo of third corrective action completed



**Completed work description of corrective
action 3**

Installed diversion ditch

Photo of fourth corrective action completed



Completed work description

Marked anchors

Completed work description of corrective action 4

Cleaned up trash

Additional photos

**Completed work description**

Compliance, installed diversion ditch , built rock run down , marked anchors , spot seeded and cleaned up trash

Summary of all work completed

Compliance, installed diversion ditch , built rock run down, marked anchors , spot seeded and cleaned up trash