

BP L48 San Juan



V2 Compliance Follow Up Form

18148169782

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200714-18148169782

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Jul 14, 2020 2:49:39 PM MDT

557 Airpark Dr, Durango, CO 81303, USA

Jul 14, 2020 2:52:25 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jul 6, 2020

Well Name

GOEGLEIN GAS UNIT 1

API Number

50670706000

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Other

Photo of first corrective action completed



Completed work description Corrective
Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated untreated Canada thistle

Photo of third corrective action completed



Completed work description of corrective action 3

treated noxious weeds

Photo of fourth corrective action completed



Completed work description

treated Canada thistle

Completed work description of corrective action 4

treated noxious weeds in reclamation and along entrance road

Completed work description

treated noxious weeds

Summary of all work completed

previous treatment dates 6/14/16, 7/14/17, 7/12/18, 7/26/19