

BP L48 San Juan



V2 Compliance Follow Up Form

18148163852

Reference Number:

20200714-18148163852

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Cole Nichols (colen@horizonenvservices.com) |
colen@horizonenvservices.com

Submission Date:

Jul 14, 2020 2:18:26 PM MDT

Location:

91 S Skylane Dr, Durango, CO 81303, USA

Jul 14, 2020 2:17:27 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jul 6, 2020

Well Name

CONRAD GAS UNIT A 1

API Number

50670690900

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Other

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

treated Canada thistle

Photo of third corrective action completed



**Completed work description of corrective
action 3**

treated musk thistle

Photo of fourth corrective action completed



Completed work description

treated musk thistle

Completed work description of corrective action 4

treated noxious weeds along road and in reclamation area

Completed work description

treated noxious weeds

Summary of all work completed

previous treatment dates 7/20/17, 7/12/18, 7/25/19