

BP L48 San Juan



V2 Compliance Follow Up Form

18148041098

Reference Number: 20200713-18148041098
Form Name: V2 Compliance Follow Up Form
Submitter Name: Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com
Submission Date: Jul 9, 2020 3:25:21 PM MDT
Location: 5854 Co Rd 307, Ignacio, CO 81137, USA
Jul 9, 2020 3:22:25 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Jul 9, 2020
Well Name	FEDERAL LAND BANK GAS UNIT D 1
API Number	50670681900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Other Install Rock Run Down Clean up Operator Debris Clean Up Contaminated Soils Repaired Berm

Photo of first corrective action completed



Completed work description Corrective Compliance
Action 1
Photo of second corrective action completed



Completed work description of corrective action 2

Installed rock run down

Photo of third corrective action completed



Completed work description of corrective action 3

Built berm

Photo of fourth corrective action completed



Completed work description

Cleaned up location

Completed work description of corrective action 4

Cleaned up stains

Additional photos



Additional photos



Additional photos



Completed work description

Fixed erosion , installed rock run down , installed new well sign cleaned up stains and cleaned up location

Summary of all work completed

Fixed erosion, installed rock run down, installed new well sign , fixed panels and hauled off trash