

BP L48 San Juan



V2 Compliance Follow Up Form

18147561511

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200707-18147561511

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Jul 7, 2020 4:54:56 PM MDT

161 Kiva Rd, Durango, CO 81303, USA

Jul 7, 2020 4:54:34 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jul 7, 2020

Well Name

TUBBS GAS UNIT 32-6-9 B 1

API Number

50670763200

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete


Compliance Inspection Actions

Seeding

Clean Up Weed Debris

Spot seeding

Photo of first corrective action completed



Completed work description Corrective Action 1

treat weeds

Photo of second corrective action completed

Completed work description of corrective action 2

blanket slopes and mulch small area

Photo of third corrective action completed

Completed work description of corrective action 3

blanket slopes

Photo of fourth corrective action completed



Completed work description

blanket slopes and mulch flat areas

Completed work description of corrective action 4

seeded and blanket/mulch areas

Summary of all work completed

seeded and blanket the slopes, seeded and mulched the flat areas.